



Effect of normal distribution and least squares method on error theory

Mohammad Reza Majidi

Bachelor's degree student in mapping, Payame Noor University, North Tehran

Email:

majidi.mfa@gmail.com

Abstract

In the Least-Square Fitting method, instead of using the absolute magnitude of the error, we consider its square. Therefore, minimizing the total number of error squares leads to the magnification, which considers smaller errors. The most common way to determine the parameters that determine the curve is to determine the direction of error reduction and a small step in that direction and repeat the process until we reach convergence. This process of resolving parameters repeatedly is also known as the "gradient descent" method. In this tutorial, we use basic matrix calculations and use them to get the parameters for the best fit of the curve.

Keywords: Errors, Least Squares, Regression, Normal Distribution, Measurement



تأثیر توزیع نرمال و روش کمترین حداقل مربعات در تئوری خطاهای

محمد رضا مجیدی

دانشجوی کارشناسی رشته نقشه برداری، دانشگاه پیام نور، تهران شمال

پست الکترونیکی:

majidi.mfa@gmail.com

تاریخ دریافت: ۱۳۹۹/۰۲/۳۱ | تاریخ پذیرش: ۱۳۹۹/۰۳/۳۱

چکیده

برازش منحنی به برآزش یک تابع از پیش تعريف شده اطلاق می‌شود که متغیرهای مستقل و وابسته را به یکدیگر مربوط می‌کند. گام اول در محاسبه بهترین منحنی یا خط، پارامتری کردن تابع خط با استفاده از متغیرهای اسکالر کمتر، محاسبه مشتق خطای نسبت به پارامترها و در نهایت محاسبه پارامترهایی است که تابع هزینه خط را کمینه می‌کند. در روش «برازش حداقل مربعات (Least-Square Fitting)»، به جای آنکه از قدر مطلق خط استفاده کنیم، مربع آن را در نظر می‌گیریم بنابراین، کمینه‌سازی مجموع مربعات خط منجر به برآزشی می‌شود که خطای کوچک‌تری را در نظر می‌گیرد. رایج‌ترین روش برای تعیین پارامترهایی که منحنی را مشخص می‌کنند، تعیین جهت کاهش خط و یک گام کوچک در آن جهت و تکرار فرایند تا جایی است که به همگرایی برسیم. این فرایند حل تکراری پارامترها به عنوان روش «گرادیان کاهشی (Gradient Descent)» (نیز شناخته می‌شود. در این آموزش، از محاسبات ماتریسی پایه استفاده می‌کنیم و آن‌ها را برای به دست آوردن پارامترها به منظور بهترین برآزش منحنی به کار می‌گیریم.

کلمات کلیدی: خطاهای، حداقل مربعات، رگرسیون، توزیع نرمال، اندازه‌گیری